

## INDUSTRY NEWS



**Reduce downtime & increase productivity with one set-up!**

Simple, Fast & Powerful

3-AXIS OnePro

4-AXIS OnePro

5-AXIS OnePro



### 3-AXIS & 5-AXIS OnePro



Pneumatically actuated workholding system, 2,000 lbs of clamping force

Maximize your 3-, 5-axis machine capabilities



One complete unit, quick set up out of box

Air plumbing  
3-axis - side of unit  
5-axis - bottom of base for through pallet air system

Can be mounted using clamping rail or integrated bolt slots.


Unit can be located using round and diamond pins on bottom surface.



### 5-AXIS OnePro

Mounts to face of indexer

Mounts to backside of indexer



The OnePro systems are the one product for mounting any workholding. NO NEED for any housing, risers, extra mounts lifters, etc. to work.

Once installed on a 4th or 5th axis, there is no need to remove it. All workholding and fixtures can be modified with two dowel pins and a retention knob at minimal cost!

Reduces the setup and qualification of any workholding or fixture from 10-60 minutes to as little as 1 minute.

When multiple fixtures are utilized, parts can be loaded offline and fixtures can be exchanged in 10 seconds or less.

Simplify scheduling, only one operation needs to be scheduled for each part.

Standardized mounting system, jobs can be run on any machine with a Kwik-Clamp.

Retention Knob is the weakest link in the system and will break if spindle crashes into the fixture, preventing catastrophic damage to the spindle/machine.

Click below for video and brochure links.

[www.kwik-clamp.com](http://www.kwik-clamp.com)

[www.raptorworkholding.com](http://www.raptorworkholding.com)